

Cofc.

Attorney Docket No.: 2207/6849
Assignee: Intel Corporation

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANTS

Gad S. Sheaffer

SERIAL NO.

09/540,432

FILED

March 31, 2000

PATENT NO.

6,944,750 B1

ISSUED

September 13, 2005

FOR

PRE-STEERING REGISTER RENAMED INSTRUCTIONS TO

EXECUTION UNIT ASSOCIATED LOCATIONS IN

INSTRUCTION CACHE

M/S: CERTIFICATE OF CORRECTION BRANCH Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450 Certificate of Mailing

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail in an envelope addressed to: M/S: CERTIFICATE OF CORRECTION BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on

Date: September 12, 2006

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

We have compared the above patent with the application as filed and have found errors in the printing of the patent. We respectfully request that the enclosed Certificate of Correction on Form PTO-1050 be issued correcting the mistakes set forth therein under authority of 35 U.S.C. §254. The exact column and line number where the errors occurred in the patent are listed on the enclosed certificate.

09/18/2006 SSESHE1 00000018 110600 6944750

01 FC:1811 100.00 DA

Certificate

SEP 2 0 2006

of Correction

Patent No. 6,944,750 B1 Issued: September 13, 2005

The errors that appear in the patent are various typographical errors made by the Applicant and therefore, a fee is required.

Please charge payment of the Certificate of Correction fee of \$100.00 to Deposit Account No. 11-0600. The Office is hereby authorized to charge any additional fees, or credit any overpayments, to Deposit Account No. 11-0600.

Respectfully submitted,

KENYØN & KENYON LLP

Dated: September 12, 2006

By:

Sumit Bhattacharya (Reg. No. 51,469)

KENYON & KENYON LLP 333 West San Carlos St., Suite 600 San Jose, CA 95110

Telephone:

(408) 975-7500

Facsimile:

(408) 975-7501

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,944,750 B1

September 13,2005

INVENTOR(S):

Gad S. SHEAFFER

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, Line 58 "unit cluster, that" should be --unit cluster that--

Column 11, Line 37 "the set of instructions are" should be --the set of instructions is --

Column 12, Line 11 "the set of instructions are" should be --the set of instructions is --

Column 12, Line 38 "the set of instructions are" should be --the set of instructions is --

KENYON & KENYON LLP

MAILING ADDRESS OF SENDER: 333 W. San Carlos, Ste 600 San Jose, CA 95110

Telephone: (408) 975-7500

PATENT NO.__ 6,944,750 B1

No. of additional copies

Date: Sept. 12, 2006

Facsimile: (408) 975-7501

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450, DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO :

6,944,750 B1

DATED

September 13,2005

INVENTOR(S):

Date: Sept. 12, 2006

Gad S. SHEAFFER

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 10, Line 58 "unit cluster, that" should be --unit cluster that--

Column 11, Line 37 "the set of instructions are" should be --the set of instructions is--

Column 12, Line 11 "the set of instructions are" should be --the set of instructions is--

Column 12, Line 38 "the set of instructions are" should be --the set of instructions is --

MAILING ADDRESS OF SENDER: 333 W. San Carlos, Ste 600

KENYON & KENYON LLP

San Jose, CA 95110

Telephone: (408) 975-7500

Facsimile: (408) 975-7501

PATENT NO. 6,944,750 B1

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.